

Issue Severity:

High: Act immediately

Medium: Bosch Security Systems strongly recommends you take the action(s) described below.

Low: Advisory

Products Affected:

- FPA-1000-UL, all versions
- FPA-1000-V2, all versions until issue is resolved (check Release Notes)

1.0 Issue

The FPA-1000 fire alarm control panels' response to an event can be delayed by up to 40 seconds when:

- You have set the system for remote programming [PPP (point-to-point protocol) monitoring is on],
- Ring count is set greater than 0.

2.0 Resolution

When you are finished with a remote programming session, set the Ring Count to 0. For details on making this setting, refer to the FPA-1000 Installation and Operation Guide (P/N: F.01U.173.607).



